

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,003,951 B2
APPLICATION NO. : 10/775788
DATED : February 28, 2006
INVENTOR(S) : Thomas Rammhofer, Udo Popp and Matthias Zink

Page 1 of 1


It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 9, lines 7 and 8 should read "a plurality of master units;
a plurality of slave unites connected to the plurality of clutches in the drive train of the
motor vehicle; and "
instead of
"a plurality of slave units connected to the plurality of clutch in the motor vehicle; and".

Column 9, line 22 should read "the interconnected pipes run coaxially." instead
of "the interconnected piped run coaxially."

Signed and Sealed this

Twenty-ninth Day of August, 2006

A handwritten signature in black ink, appearing to read "Jon W. Dudas", is written over a rectangular area that has been shaded with a stippled pattern.

JON W. DUDAS
Director of the United States Patent and Trademark Office